## **SITE INSPECTION - RESIDENTS MEMO**




FH Reference: 125592	Project : Berryhill Landslip Remedial Works	Date of Site Visit: 03/01/2020
inspections of the quarry November 2019) and the in early 2020.	ncil (MDC) have appointed Fairhurst to wall between completion of the emergency recommencement of the permanent works in on Friday 3 <sup>rd</sup> of January 2019, the weather	esponse works (w/e 24 <sup>th</sup> this portion of the quarry
A photographic record of the quarry has been collated and is being updated on inspection and no obvious visible changes have been noted from the previous site visit (23/12/2019). No further noticeable debris was noted in the rock trap at the toe of the slope. Fairhurst are not aware of any reported issues to MDC and the garden heras fencing remained in situ as agreed. No increase in risk has been determined from the recent inspection.		
If residents see or hear anything associated with the cliff face, please call 01623 463 050 to report this to the Council.		
Photographs included ov	verleaf.	
Prepared by: Joshua Blacker Engineering Geologist, Fai	rhurst	Date: 03/01/2020
Distribution:		

Mansfield District Council - James Biddlestone


For distribution to affected residents on Stone Bank and Bank End Close.




Photograph 1 : Looking along the southern flank of the quarry to the south west corner (Image taken on 03/01/2020)




Photograph 2: Previous failure scar (Image taken on 03/01/2020)



Photograph 3: Looking west to the south west quarry corner (Image taken on 03/01/2020)



Photograph 4: Looking at western flank and previous failure scar (Image taken on 03/01/2020)



Photograph 5: Looking north to the end of Unit 8. Debris from small failure reported on the  $24^{th}$  November 2019. Note two grass clumps, approx.  $30 \text{cm}^2$  on top of the previous small failure (Image taken on 03/01/2020).