

FH Reference: 125592	Project : Berryhill Landslip Remedial Works	Date of Site Visit: 23/12/2019

Mansfield District Council (MDC) have appointed Fairhurst to undertake regular site inspections of the quarry wall between completion of the emergency response works (w/e 24th November 2019) and the commencement of the permanent works in this portion of the quarry in early 2020.

During a recent inspection on Friday 23rd December 2019, the weather was cloudy with sunny spells and intermittent drizzle.

A photographic record of the quarry has been collated and is updated after each inspection. Only small, local visible changes have been noted from the previous site visit (16/12/2019). Two vegetation clumps approximately 30cm² were present on top of a small scale failure (previously reported on the 24/11/2019) located in the rock trap at the toe of the slope. Fairhurst are not aware of any reported issues to MDC and the garden heras fencing remained in situ as agreed. No increase in risk has been determined from the recent inspection.

If residents see or hear anything associated with the cliff face, please call 01623 463 050 to report this to the Council.

Photographs included overleaf.

Prepared by: Joshua Blacker	Date: 23/12/2019
Engineering Geologist, Fairhurst	
Distribution:	
Mansfield District Council – James Biddlestone	

For distribution to affected residents on Stone Bank and Bank End Close.

FAIRHURST




Photograph 1 : Looking along the southern flank of the quarry to the south west corner (Image taken on 23/12/2019)





Photograph 2: Previous failure scar (Image taken on 23/12/2019)


FAIRHURST



Photograph 3 : Looking west to the south west quarry corner (Image taken on 23/12/2019)


SITE INSPECTION - RESIDENTS MEMO

FAIRHURST



Photograph 4 : Looking at corner of western and southern flank (Image taken on 23/12/2019)

FAIRHURST



Photograph 5: Looking north to the end of Unit 8. Debris from small failure reported on the 24th November 2019. Note two vegetation clumps, approx. 30cm² on top of the previous small failure (Image taken on 23/12/2019).