

| | | |
|---|---|-----------------------------------|
| FH Reference: 125592 | Project : Berryhill Landslip Remedial Works | Date of Site Visit: 29/11/2019 |
| <p>Mansfield District Council (MDC) have appointed Fairhurst to undertake regular site inspections of the quarry wall between completion of the temporary emergency response works (w/e 24th November 2019) and the commencement of the permanent works in this portion of the quarry proposed in early 2020.</p> <p>During a recent inspection on Friday 29th November 2019, the weather was fine and dry during the site visit having cleared of fog earlier in the day. It is understood that rain had fallen earlier that week fairly consistently, but not heavily.</p> <p>A photographic record of the quarry has been collated and is being updated on each inspection and no obvious visible changes have been noted from the previous site visit (24/11/2019). No further noticeable debris was noted in the rock trap at the toe of the slope. Fairhurst are not aware of any reported issues to MDC and the garden herrace fencing remained in situ as agreed. No increase in risk has been determined from the recent inspection.</p> <p>If residents see or hear anything associated with the cliff face, please call 01623 463 050 to report this to the Council.</p> <p>Photographs included overleaf.</p> | | |
| Prepared by: C Barber Technical Manager, Fairhurst | | Date: 29/11/2019 |
| Distribution: | | |
| <p>Mansfield District Council –James Biddlestone</p> <p>For distribution to affected residents on Stone Bank and Bank End Close.</p> | | |




Photograph 1 : Location of mass failure from 5th November 2019



Photograph 2: looking to the eastern end of the temporary works



Photograph 3 : Looking west to the south west quarry corner



Photograph 4 : South west Quarry Corner



Photograph 5 : Looking north to the end of Unit 8



Photograph 6 Looking south to the south western corner