SITE INSPECTION – FAILURE RECORD MEMO




FH Reference: 125592	Project : Berryhill Landslip Remedial Works	Date of Site Visit: 24/11/2019
the quarry between com	cil have appointed Fairhurst to undertake apletion of the emergency response works of the permanent works in this portion of the	(w/e 24 th November 2019)
the rear of No. 84 Stone occurred between the e	ion on Sunday 24 th November 2019, a smale Bank (Unit 8 of the quarry wall face). The vening of Friday 22 nd November and Sundahlis failure to the council.	ne failure appears to have
photographs, and has e small (c.2m³) and has b cliff and the soil bund)	down from the upper part of the cliff face, expose some vegetation roots. The volumbeen contained within the rock trap (the are as indicated on the photographs. The material with the ground to sand, with the excessible photographs below.	ne of material is relatively ea between the toe of the ajority of the material has
There may be ongoing protection measures cur and the measures advis the herras fencing and increase in risk has be	surrounding areas of cliff have not identife small ravelling failures, as is known to corrently in place, including the rock trap, conceed in the 'Safe Return Letter' – including relimited time spent in back gardens, are concended the cliff face, please call 01623 463 050 to	occur at the quarry. The crete barriers and bunding, educed garden area within insidered appropriate. No If residents see or hear
Photographs included ov	verleaf.	
Prepared by: C Barber		Date: 24/11/19

Distribution:


Technical Manager, Fairhurst

Mansfield District Council - Sarah Troman and James Biddlestone


For distribution to affected residents on Stone Bank and Bank End Close.



Photograph 1: Location of small failure



Photograph 2: Debris material contained within rock trap



Photograph 3 : Debris at base of cliff face near extents of emergency work, to rear of No. 84 Stone Bank